






FLP-5051BPM



TECHNICAL DRAWING



TEMP. & WATER PRESSURE REQUIREMENTS




Working Pressure: 1~3 bar




Required Temperature: 5-65°C


Note: Above are the recommended values for getting Conventional Output.


DO ✓



DON'T ✗












Apply soft cotton cloth




Apply soft cotton cloth



✗ DON'T

Don't apply Scrub

✗ DON'T



Steps & Cleaning agents requirements for Aerator Cleaning.

